

#### Symaro

## **Duct sensors**

for relative humidity and temperature

# QFM21..

Operating voltage AC 24 V / DC 13.5...35 V Signal output DC 0...10 V / 420 mA for relative humidity Signal output DC 0...10 V / 420 mA / T1 / LG-Ni 1000 for temperature Measuring accuracy 3 % r. h. within the comfort range Range of use -15 +60 ¢7095 % r. h. (non-condensing)

The QFM21.. duct sensors are for use in air ducts of ventilation and air conditioning plant for acquiring:

- The relative humidity and The temperature.
- The sensors are used as:
- Control sensors in the supply or extract air
- Reference sensors, e.g. for shifting the dew point
- Limit sensors, e.g. in connection with steam humidifiers
- Limit sensors, e.g. for measured value indication or for connection to a building automation and control system
- Sensors for enthalpy and absolute humidity, together with SEZ220 (see Data Sheet N5146)

#### Type summary

Type reference	Temperature measuring range	Temperature signal output	Humidity measuring range	Humidity signal output	Operating voltage
QFM2100	None	None	0100 %	active, DC 010 V	AC 24 V or DC 13.535 V
QFM2101	None	None	0100 %	active, 420 mA	DC 13.535 V
QFM2120	- 35+50 ç™^	passive, LG-Ni 1000	0100 %	active, DC 010 V	AC 24 V or DC 13.535 V
QFM2140	- 35+50 ç™^	passive, T1 (PTC)	0100 %	active, DC 010 V	AC 24 V or DC 13.535 V
QFM2160	050 ç <sup>™</sup> / - 35+35 ç <sup>™</sup> or - 40+70 ç <sup>™</sup>	active, DC 010 V	0100 %	active, DC 010 V	AC 24 V or DC 13.535 V
QFM2171	050 ç <sup>tm</sup> / - 35+35 ç <sup>tm</sup> or - 40+70 ç <sup>tm</sup>	active, 420 mA	0100 %	active, 420 mA	DC 13.535 V

#### Ordering and delivery

When ordering, please give name and type reference, e.g.: Duct sensor **QFM2120** The sensor is supplied with mounting flange and cable entry gland M16.


#### **Equipment combinations**

All systems and devices capable of acquiring and handling the sensor DC 0...10 V, 4...20 mA, LG-Ni 1000 or T1 output signal.


When using the sensors for minimum or maximum selection, for averageing, or to calculate enthalpy, enthalpy difference, absolute humidity, and dewpoint, we recommend to use the SEZ220 signal converter (see Data Sheet N5146).

#### Function


Relative humidity	The sensor acquires the relative humidity in the air duct via its capacitive humidity sensing element whose electrical capacitance changes as a function of the relative humidity.			
	The electronic measuring circuit converts the sensors signal to a continuous DC 010 V or 420 mA signal, which corresponds to 0100 % r. h.			
Temperature	The sensor acquires the temperature in the air duct via its sensing element whose electrical resistance changes as a function of the temperature. Depending on the type of sensor this change in resistance is converted either to an active DC 010 V or 420 mA output signal corresponding to a temperature range of $0.50 \text{ g}^{\text{TM}}$ , 35+35 C, or $-40+70$ C. The measuring range can be selected. The temperature is provided as a simulated passive LG-Ni 1000- or T1-output signal ( $\cong 3550 \text{ g}^{\text{TM}}$ ) as an alternative to the active output signal.			
Simulated passive output signal	The measuring current of systems/devices for acquiring the electrical resistance of the passive sensor differs greatly and impacts self-heating of the temperature sensing element at the end of the measuring tip. To compensate the impact, the passive output signal is simulated with an electronic circuit.			
Sensing elements, simulated LG-Ni 1000				







Legend



#### **Mechanical design**

The duct sensor consists of a housing, a printed circuit board, connection terminals, a mounting flange and an immersion rod having a measuring tip.

30

[DC V]

40

The 2-sectional housing comprises a base and a removable cover (snap-on design). The measuring circuit and the setting element are located on the printed circuit board inside the cover, the connection terminals on the base.

The sensing elements are located at the end of the measuring tip and protected by a filter cap.

Cable entry is made via the screwed cable gland M16 supplied with the sensor. Immersion rod and housing are made of plastic and are rigidly connected.

The sensor is fitted with the mounting flange supplied with the sensor. The flange is to be placed over the immersion rod and then secured in accordance with the required immersion length.

O Range 1 2 3	0	Measuring range			Test	function a	active	
		1 2 3		U1	U2	BS-MS	1	12
			000 000	10 V	5 V	≙ 20 °C	20 mA	12 mA
			0000	5 V	10 V	≙ 75 °C	12 mA	20 mA
			000	0 V	5 V	≙ 20 °C	4 mA	12 mA
				5 V	οv	≙-35 °C	12 mA	4 mA

The setting element is located inside the cover. It comprises 6 pins and a jumper. It is used to select the required measuring range and to activate the test function.

#### Setting element

	<ul> <li>The different jumper settings have the following meaning:</li> <li>For the passive temperature measuring range:</li> <li>Jumper in the middle position (R2) = -35+50 ç<sup>TM</sup> (factory setting)</li> <li>For the active temperature measuring range:</li> <li>Jumper in the left position (R1) = -35+35 ç<sup>TM</sup> ,</li> <li>Jumper in the middle position (R2) = 050 ç<sup>TM</sup> (factory setting)</li> <li>Jumper in the middle position (R3) = -40+70 ç<sup>TM</sup> ,</li> <li>For activating the test function:</li> <li>Jumper in the horizontal position: The values according to the table "Test function active" will be made available at the signal output.</li> </ul>
Malfunction	Should the temperature sensor become faulty a voltage of 0 V (4 mA) will be applied at signal output U2 (I2) or signal output BS-MS becomes high impedance (>1 M) after 60 seconds, and the humidity signal at signal output U1 (I1) will reach 10 V (20 mA). Should the humidity sensor become faulty a voltage of 10 V (20 mA) will be applied at signal output U1 (I1) after 60 seconds, and the temperature signal will remain active.

#### Accessories

Name	Type reference
Filter cap (for replacement)	AQF3101

### Engineering notes

	A transformer for safety extra low-voltage (SELV) with separate windings for 100 % duty is required to power the sensor. When sizing and protecting the transformer, local safety regulations must be complied with. When sizing the transformer, the power consumption of the duct sensor must be taken into consideration. For correct wiring, refer to the Data Sheets of the devices with which the sensor is used. The permissible cable lengths must be considered.
Cable routing and cable selection	It must be considered for routing of cables that the longer the cables run side by side and the smaller the distance between them, the greater electrical interference. Shielded cables must be used in environments with EMC problems. Twisted pair cables are required for the secondary supply lines and the signal lines.
Note to <b>QFM2171</b>	Terminals G1(+) and I1(-) of the humidity output must always be connected to power, even if only terminals G2(+) and I2(-) of the temperature output are used!

#### Mounting notes

Location	Mount the sensor in the center of the duct wall. If used together with steam humidifiers, the minimum distance after the humidifier must be 3 m to max 10 m.
	Fit the sensor in the extract air duct if the application involves dew point shifting.
	Fit only the flange to the duct wall. The sensor is then inserted through the flange and engaged.
Caution!	To ensure degree of protection IP 54, fit the sensor with the cable entry pointing downward.
	The sensing elements inside the measuring tip are sensitive to impact. Avoid any impact on mounting.
Mounting instructions	The mounting instructions are printed on the inside of the package of the device.
Chemical vapors	It is of great importance to understand that a humidity sensor is a sensitive measure device and needs to be handled with care. Chemical vapors at high concentration in combination with long exposure times may offset the sensor reading.
Commissioning notes	
	Check wiring before switching on power. The temperature measuring range must be selected on the sensor, if required.
	Wiring and the output signals can be checked by making use of the test function (refer to "Mechanical design").
	To ensure the accuracy of the temperature measurement of the QFM2120, QFM2140 the test function has to be activated and on the controller side the values have to be adjusted.
$\bigwedge$	We recommend not to use voltmeters or ohmmeters directly at the sensing element. In
	the case of the simulated passive output signals, measurements with commercially
	available meters cannot be made (measuring current too small).
Disposal	
	The devices are considered electronics devices for disposal in term of European Di-
X	rective 2012/19/EU and may not be disposed of as domestic waste.
∕┢━┛╲	Dispose of the device via the channels provided for this purpose.

Comply with all local and currently applicable laws and regulations.


#### Technical data

Power supply	Operating voltage	AC 24 V 20 % or DC13.535 V (SELV) or
		AC/DC 24 V class 2 (US)
	Frequency	50/60 Hz at AC 24 V
	External supply line protection	Fuse slow max. 10 A
		or Circuit breaker max. 13 A Characteristic B, C, D according to EN 60898 or
		Power source with current limitation of max. 10 A
	Power consumption	1 VA
Cable lengths for measuring signal	Perm. cable lengths	See data sheet of the device handling the signal
Functional data of	Range of use	095 % r. h. (non-condensing)
numidity sensor	Measuring range	0100 % r. h.
	Measuring accuracy at 23 ç™^and AC/DC 24 V in 095 % r. h.	5 % r. h.
	3070 % r. h.	3 %, r. h. typically
	Time constant at 050 ç™^and 1080 % r.h.	< 20 s
	Perm. air velocity	20 m/s
	Output signal, linear (terminal U1)	DC 010 V
	Output signal, linear (terminal I1) Burden	420 mA
Functional data of temperature sensor with QFM2160,	Measuring range	050 ç <sup>™^</sup> (R2 = factory setting), - 35+35 C (R1) or - 40+70 ç <sup>™^</sup> (R3)
QFM2171	Measuring accuracy at AC/DC 24 V in	
	23ç™^	0.3 K
	1535 ç™^	0.7 K
	- 35+50 ç™^	1 K
	Time constant	< 3.5 min. in with 2 m/s moved air
	Output signal, linear (terminal U2)	DC 010 V
	Output signal, linear (terminal I2)	max. 1 mA 420 mA
		/-40+70 ç™^
	Burden	See "Function"
Functional data of temperature	Measuring range	- 35+50 ç™^
Sensor with	Sensing element simulated, corresponding to	
QFM2120, QFM2140	QFM2120	LG-Ni 1000
	QFM2140	T1 (PTC)
	Measuring accuracy at AC/DC 24 V in the range of	
	23ç™^	0.3 K
	20γ 1535 ç™^	0.7 K
	- 35+50 ç™^	1 K
	Time constant	< 3.5 min. in with 2 m/s moved air
	Perm. measuring current with	
	QFM2120	1.184.21 mA
	QFM2140	0.531.89 mA
Degree of protection	Protection degree of housing	IP54 according to EN 60529 in built-in state
	Protection class	III according to EN 60730-1
Electrical connections	Connection terminals for	1 2.5 mm <sup>2</sup> or 2 1.5 mm <sup>2</sup>
	Cable entry gland (enclosed)	M 16 x 1.5

Environmental conditions	Operation	IEC 60721-3-3		
	Climatic conditions	Class 3K5		
	Temperature (housing with electronics)	- 15+60 ç™^		
	Humidity	095 % r. h. (non-condensing)		
	Mechanical conditions	Class 3M2		
	Transport	IEC 60721-3-2		
	Climatic conditions	Class 2K3		
	Temperature	- 25+70 ç™^		
	Humidity	<95 % r. h.		
	Mechanical conditions	Class 2M2		
Materials and colors	Base	Polycarbonate, RAL 7001 (silver-grey)		
	Cover	Polycarbonate, RAL 7035 (light-grey)		
	Immersion rod	Polycarbonate, RAL 7001 (silver-grey)		
	Filter cap	Polycarbonate, RAL 7001 (silver-grey)		
	Mounting flange	PA66 GF35 (black)		
	Cable entry gland	PA, RAL 7035 (light-grey)		
	Sensor (complete assembly)	Silicone-free		
	Packaging	Corrugated cardboard		
Directives and Standards	Product standard	EN 60730-1		
		Automatic electrical controls for household		
		and similar use		
	Electromagnetic compatibility (Applications)	For use in residential, commerce, light-		
		industrial and industrial environments		
	EU Conformity (CE)	CE1T1864xx <sup>2)</sup>		
	RCM Conformity	CE1T1864en_C1 2)		
	UL	UL 873, http://ul.com/database		
Environmental	The product environmental declaration CE1E1864 <sup>2)</sup> contains data on environmentally compatible p			
compatibility	uct design and assessments (RoHS compliance, materials composition, packaging, environmental			
	benefit, disposal).			
Veight	Incl. packaging			
	QFM21	Approx. 0.18 kg		

2) The documents can be downloaded from http://siemens.com/bt/download.


#### **Connection terminals**



Note on connection terminals of the **QFM2171**:

Terminals G1(+) and I1(-) for the humidity output must always be connected to power, even if only the temperature output G2(+) and I2(-) is used!

CE1N1864en 2018-03-23



Drilling plan with (without) mounting flange

Dimensions in mm

Issued by: Siemens Switzerland Ltd. Building Technologies Division International Headquarters Theilerstrasse 1a CH-6300 Zug Tel. +41 58 724 2424 www.siemens.com/buildingtechnologies

#### 10/10

Siemens Building Technologies Duct sensors QFM21..

Siemens Switzerland Ltd 2006 Technical specifications and availability subject to change without notice.